



[www.worldracinggroup.com](http://www.worldracinggroup.com) [www.dirtcar.com](http://www.dirtcar.com) [www.superdirtseries.com](http://www.superdirtseries.com)

## **2013 Rule(s) Bulletin**

Bulletin: 2013-2 – April 4<sup>th</sup>, 2013

The following rule amendments are in regard to the following division, the Super DIRTcar Big Block Modified Series and/or DIRTcar Big Block Modifieds:

### **15.1.7 Lubrication/Oiling System/Oil Cooler**

E.) The oil pan on conventional DIRTcar Big Block and the DIRTcar 500 engines must have a one (1") inch diameter inspection hole on the left side to permit inspection. If no inspection hole is present the oil pan must be removed for inspection.

### **15.0-A Super DIRTcar Series / DIRTcar Big Block Modified**

#### **15.1.9 – Transmission/Driveline and Driveline Components**

F.) Driveline components made of carbon fiber, titanium and/or other materials (considered exotic) will not be permitted.

#### **15.1.10 – Driveshaft**

E.) Carbon fiber, titanium and/or other materials (considered exotic) will not be permitted.

#### **15.1.12 – Rear End**

F.) Carbon fiber, titanium and/or other materials (considered exotic) for any rear end component will not be permitted.

Scott Fremouw, DIRTcar Technical Advisor

Joe Skotnicki, DIRTcar Northeast  
World Racing Group  
(704-796-4566)

Scott Fremouw

